User Manual

Plustrace I1 Single use Temperature Indicator



Operation Instruction

01 Push the only button for 5 seconds and notice GREEN LED flashes three times to indicate a successful start

02 Attach the started inno- check to your shipment

OK OK (flash 1 time for every 30 seconds)

UNDER Low threshold activated (flash 1 time for every 30 seconds)

OVER High threshold activated (flash 1 time for every 30 seconds)

03 Push the only button for 5 seconds and notice RED LED flashes three times to indicate a successful stopping Check the status after receiving the goods

Operation Instructions

Start/Stop

Status	Action	LED confirmation
Start Indicator	5 sec pushing button	OK LED flashing 3 times
Stop Indicator	5 sec pushing button	ALERT LED flashing 3 times

Status request by pushing button 1 time

Status	Action	LED confirmation
Not Started	Push button 1 time	OK LED+ ALERT LED Flash one time
Recording-OK	Push button 1 time	OK LED Flash one time
Recording-Low Alarm	Push button 1 time	Blue LED Flash one time
Recording-High alarm	Push button 1 time	ALERT LED Flash one time
Recording- High and low Alarm	Push button 1 time	Blue LED and ALERT LED flash one time
Stopped-OK	Push button 1 time	OK LED Flash two times
Stopped-Low Alarm	Push button 1 time	Blue LED Flash two times
Stopped-High alarm	Push button 1 time	ALERT LED Flash two times
Stopped- High and low Alarm	Push button 1 time	Blue LED and ALERT LED flash one time

Using Notes

1, Take care of the Expiry date
2, Don't hold the indicator too long in your hand (False alarm through self-heating)
3, Only for disposable use